



General Electric Company
P.O. Box 488, Burlington, IA 52601
319 753-8400

July 17, 1995

Mr. Don Lininger
Environmental Protection Agency
Region VII
RCRA/Iowa Section
726 Minnesota Avenue
Kansas City, KS 66101

RECEIVED

JUL 21 1995

IOWA SECTION

Re: Closure of EPA RCRA ID #IAD005272703

Per our closure plan, we were to notify you when we had disposed of the closure-generated wastes. The floor sweepings from the Outdoor Storage Building, Sludge Storage Area, and the "Small" Safety Storage Building were placed into a one cubic yard bag and picked up by Clean Harbors of Chicago. The disposal manifest #IL6625787 is attached. The floor sweepings from the Cyanide Storage area and the personal protective equipment were placed into a 55 gallon drum and picked up by Clean Harbors of Braintree. The disposal manifest #MAH712501 is attached. The decontamination and rinse waters generated by the closure were all processed/destroyed in our on-site waste water treatment system during the week of 6/26/95. Finally, the plywood flooring from the Safety Storage Building was cut into pieces and placed into a one cubic yard bag and picked up by Clean Harbors of Chicago. This bag is also on manifest #IL6625787.

I trust that this information fulfills your need for information of the disposal of the wastes generated. please address any further questions to me.

Sincerely,

T. Max Pickel
Mgr. EHS
General Electric Switchgear Operations
Burlington, IA



R00024390

RCRA Records Center

PLEASE TYPE

(Form designed for use on elite (12-pitch) typewriter.)

EPA Form 8700-22 (Rev. 6-87)

Form Approved. OMB No. 2050-0039, Expires 9-30-94

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest
Document No.

2. Page 1

Information in the shaded areas is not
required by Federal law, but is required by
Illinois law.

3. Generator's Name and Mailing Address

Location If Different

A. Illinois Manifest Document Number

IL6625787

FEE PAID
IF APPLICABLE

4. *24 HOUR EMERGENCY AND SPILL ASSISTANCE NUMBERS*

5. Transporter 1 Company Name

6. US EPA ID Number

B. Illinois

Generator's ID

C. Illinois Transporter's ID

D. Transporter's Phone

E. Illinois Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address

10. US EPA ID Number

G. Illinois
Facility's
ID

H. Facility's Phone

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

No.

Type

13.
Total
Quantity14.
Unit
Wt/VolI.
Waste No.a. NO WASTE PAINT RELATED MATERIAL (F003, F005, D001)
3. UN1263, PG11

004 DM 00220 G

XXI F003
Authorization Number
000224

b. HAZARDOUS WASTE SOLID, N.O.S. (F003), 9, NA3077, PG11

016
CY 000.16 YXXI F003
Authorization Number
000224c. NO HAZARDOUS WASTE SOLID, N.O.S. (F003, F005)
(XYLENE, TOLUENE), 9, NA3077, PG11

003 DM 001.65 G

XXI F003
Authorization Number
000224d. NO HAZARDOUS WASTE SOLID, N.O.S. (D003), (LEAD), 9
NA3077, PG11

003 DM 001.65 G

XXI D003
Authorization Number
000224

J. Additional Description for Materials Listed Above

K. Handling Codes for Wastes Listed Above
In Item #14

G = Gallons Y = Cubic Yards

15. Special Handling Instructions and Additional Information

UN1263, PG11

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by
proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway
according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

Date
Month Day Year
07 06 95

ERIC S. RANKIN

Eric S. Rankin

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date
Month Day Year

Eric S. Rankin

Eric S. Rankin

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

Date
Month Day Year



COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF ENVIRONMENTAL PROTECTION
DIVISION OF HAZARDOUS WASTE
One Winter Street Boston, Massachusetts 02108

WK 4951

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

National Response Center (800) 424-8802.

In case of emergency or spill, immediately call

GENERATOR

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. IA00527000		Manifest Document No. 44336		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.			
3. Generator's Name and Mailing Address GENERAL ELECTRIC COMPANY SWITCH GEAR DIVISION PO BOX 488 510 EAST AGENCY RD BURLINGTON, IA 52601						A. State Manifest Document Number MA H 712501					
4. Generator's Phone (617) 752-8508						B. State Gen. ID PO BOX 488 510 EAST AGENCY RD BURLINGTON, IA 52601					
5. Transporter 1 Company Name EPA, S. 1005, Inc.						C. State Trans. ID P114670					
7. Transporter 2 Company Name						D. Transporter's Phone (617) 847-1800					
9. Designated Facility Name and Site Address CLEAN HARBORS OF BRAINTREE, INC 385 QUINCY AVE BRAintree, MA 02184						E. State Trans. ID					
10. US EPA ID Number MA053452637						F. Transporter's Phone ()					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) a. PO. WASTE POISONOUS SOLIDS, N.O.S. (F007, F008) (CYANIDE), 6.1, UN2811, PG11						12. Containers No. Type 002 DM 00100		13. Total Quantity Unit P		Waste No. F007 F008	
J. Additional Descriptions for Materials Listed Above (include physical state and hazard code.) a. (S)(R)(T)						K. Handling Codes for Wastes Listed Above a. b. c. d.					
15. Special Handling Instructions and Additional Information Emergency Contact: 1-800-OIL-TANK 645-8265						16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name EPA, S. 1005, Inc.						Signature [Signature]		Date Month Day Year 07/17/95			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Michael E. Kasal						Signature [Signature]		Date Month Day Year 07/17/95			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name						Signature		Date Month Day Year			
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						Date Month Day Year					
Printed/Typed Name						Signature		Date Month Day Year			